Work Orde Tuesday, Novem			. :	*76	3497*					
Item ID:	D3325-041			Accept	*N900	040	100)*	Setup Sta	rt *N!
Revision ID:									Sto	D *N.14
Item Name:	Basket Lid As	sembly								, "IZI:
Start Date:	11/15/2011	Start Qty: 1.00	*1*		Cust Item	ID:				
Required Date:	11/25/2011	Req'd Qty: 1.00	*1*		Customer:					
Reference:			•						~.	
Approvals:	Process Pla	n: //	Date:////-/5	Tooling:	D	ate:)	Run Sta	" *NI
прриочина	QC:		Date:	SPC (Y/N):		ate:		:	Sto	^р *\II
	QC:		Date	Si C (1/11).		aic				1711
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hour	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number
Draw Nbr	Rev	ision Nbr								
D3325	Rev	В								
100		Mar Market Co.		0.00	1					
100		Large Fab						14	Ø	
Large Fab		Memo		0.00	(p(11.11.	24			_ /	
Large Fab		1-Cut tub	oes as per Dwg D3325	· ·		•				
		2D3325- 3D3325-	Number Description 1EndTube / 09/6 3Interior Tube / 09/6 5Full Lengh Tube / 09/6	7				,		* 4;

Identify parts appropriately

2-Remove all markings from material

4-Deburr as required

		7 = 1 4							••
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
								:	
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date: _	
		esolution:							
NCR:	·		WORK ORD	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC	1-21-6	Corrective Action Section			cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
-									

Work Orde Tuesday, Novem				*764	197*				· · · · · · · · · · · · · · · · · · ·			Page 2
Item ID: Revision ID: Item Name:	D3325-041 Basket Lid As	ssembly		Accept	*N900	040	100)*	Setup	Start Stop		S1* S2*
Start Date: Required Date: Reference:	11/15/2011 11/25/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item II Customer:	D:						
Approvals:	Process Pla	ın:	Date:	Tooling:		nte:			Run	Start Stop	*N *N	R1* R2*
Sequence ID/ Work Center II 110 *110* QC Quality Control)	Operation Description QC9- Inspect visual per Memo	QS1004- Fusion Welds	Set Up/ Run Hours 0.00	Tool ID	Tool#	Code	Accept Qty	Qty	•	Reject Number	Insp. Stamp
120 *120* QC Quality Control		QC5-Inspect part comp	leteness to step on W/O	0.00 W	w/24							
121 *121* HandFinish		Pressure Wash per QSI0 Memo	05 4.3	0.00			/	XQ	14	M] [H	4/20

Hand Finishing

Work Orde				*764	197*			-		Page 3
Item ID: Revision ID:	D3325-041			Accept	*N900	04010	n * Se	tup Star	14.	\1 *
Item Name:	Basket Lid As	ssembly						Stop	, *N:	32*
Start Date:	11/15/2011	Start Qty: 1.00	*1*		Cust Item I	D:				
Required Date:	11/25/2011	Req'd Qty: 1.00	*1*		Customer:					
Reference:							D	Cto.		
Approvals:	Process Pla	ın:	Date:	Tooling:	Da	ıte:	Rı -		I/I L	₹1*
	QC:		Date:	SPC (Y/N):	Da	nte:	-	Stop	`*NF	₹2*
Sequence ID/ Work Center II	D	Operation Description	,,,	Set Up/ Run Hours	Tool ID	Tool # Plan Code	Accept Qty	Reject Qty	•	Insp. Stamp
*130 *130* Powdercoat Powder Coating	(1)	White Gloss(Ref:4.3.5.1 Memo 1ST COAT: START TIN	a'40	0.00 0.00	0 F	1,	XY	M.	J Mi	11/2
PUM	34' <i>4</i> 1	FINISH TIN **** 2ND COAT START TIN	ME:) ,						
140 *110*		QC3- Inspect Part Finish	1	0.00			1 <i>1</i> 5	R 11-	11. 28	٠

0.00

Memo

Quality Control

Work Orde				*764	197*						Pa	age 4
Item ID: Revision ID: Item Name:	D3325-041 Basket Lid As	ssembly		Accept	*N900	040 <i>′</i>	100	* 5	Setup	Start Stop	*NS1 *NS2	*
Start Date: Required Date: Reference:	11/15/2011 11/25/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:						
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		ate:		F	Run	Start Stop	*NR1 *NR2	
Sequence ID/ Work Center II 150 *150* Packaging	0	Operation Description Identify as per dwg & Stoo	k Location: 6 · A W/0.764	Set Up/ Run Hours 0.00	Tool ID			Accept Qty	Rej Oty	•	Reject Insp. Number Stam	
Packaging		QC21- Final Inspection - V	Work Order Release	0.00			·			1	111/29	4

160

Quality Control

Memo

0.00

Picklist Print

Tuesday, November 15, 2011 4:00:07 PM

Work Order ID: 76497

76497

Parent Item: D3325-041

D3325-041

Parent Item Name:

Basket Lid Assembly

Start Date: 11/15/2011

Required Date: 11/25/2011

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A05.02.09New issueKJ/JLM

IPP Rev:B 08-12-16 attach DEO DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3328-1		Manufactured	No			100	Each	17.0000	2	2			
D3328-1 Basket Hinge									**	(pl	//./	/ ∙∋	/
				Location		Loc		Loc Code					
			•	WA005	33871		17 17		7	2)	_		
D3349-1		Manufactured	No			100	Each	22.0000	2	2	- 2 `		
D3349-1 Spacer Bushing									**	(/		٠٤١	
				Location		Loc	<u>Oty</u>	Loc Code					
				WA005	44401		22 22		_	(2)	-		
D3352-1		Manufactured	No			100	Each	11.0000	1		<i>/</i>		
D3352-1 Label Plate									**		Plic.	//·à	<u>/</u>
				Location		Loc		Loc Code					•
				WA005	41925		11 11						
D3367-1		Manufactured	No			100	Each	8.0000	2	2			
D3367-1 Mounting Bracket									**	(7	0//	-//-2	1
J				Location		Loc (<u>Oty</u>	Loc Code					
				WA005	12220		8		7	5	5		
				(13228		8		\in		_		

Tuesday, November 15, 2011 4:00:08 PM

Work Order ID: 76497

76497

Parent Item:

D3325-041

D3325-041

Parent Item Name: Basket Lid Assembly

Start Date: 11/15/2011

Required Date: 11/25/2011

Start Qty: 1.00

**

Required Qty: 1.00

M4130NTS0.500W.035

Purchased

No

100

307.3682

20.5416

21.62274

M4130NTS0 500W 035

4130 Square tube .500 x .500 x .035w

Location

MAT034

109127

109385

112786 119441

119506


Loc Oty 307.3682

f

158.152 15.75 39.2488

57.8774 36.34 Loc Code

21.6227




Ø141-15


	•							
W/O:		100	WC	RK ORDER CHANG	ES			·
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date Qt	y Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	JORY:	NCR: Vas I	No DOA:	Date	
		esolution:						
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR)		
DATE	STEP	Description of NC	Initial	Corrective Action Section	ion B	Verificatio		Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Section C	Chief Eng	QC Inspector
								i
				·				



DESIGN #H	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO,	
CHECKED,	APPROVED:	DRAWING NO. D3325	REV. B SHEET 2 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



VIEW A-A



DEO ATTACHED


Copyright © 2004 by DAR! AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

	•								
W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	s No DC	A:	Date:	
		olution:							
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial		tion B		cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Dat		tion C	Chief Eng	QC Inspector
									•
								-	



DESIGN PH	DRAWN BY	DART AEROSPA HAWKESBURY, ONTARIO	
CHECKED	APPROVED	DRAWING NO. D3325	REV. B SHEET 3 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									:
Part No		PAR #:	Fault Cat	egory:	_ NCR: Yes	No D	QA:	_ Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C (Closed: _		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE (NC	R)			
DATE	STEP	Description of NC			ion B	Veri	fication	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Se	ction C	Chief Eng	QC Inspector

DRAWING	NO.	TITLE		REV. B	DART AE	ROSPACE	LTD	D.E.O. NO.		SHEET NO.	SCALE
D3325			LID ASSEMBLY			ERING OR		D3325-B-	1	SHEET 1 OF 1	NTS
DRAWN	AJS		CHECKED		MFG. APPR.	77	AP	PROVED	140	DE APPR.	
DATE	08 11	28	DATE	08.11.28	DATE	08.12.01	DA	TE	08.12.01	DATE 08.12.01	

1) SHEET 1 MODIFY PARTS LIST AS SHOWN:

PART LIST FOR D3325-041 BASKET LID ASSEMBLY

Part No.	Quantity	Description

IS:

		
MS20600AD4W5	32	RIVET

WAS:

RIVET MS20600AD4W3 32

2) UPDATE SHEET 3 DETAIL B ACCORDINGLY.

14997

COPYRIGHT © 2008 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WELL THE PERMISSION FROM DART AEROSPACE LTD.

Dart Aerospace Ltd	D	art	Aer	osp	ace	Ltd
--------------------	---	-----	-----	-----	-----	-----

W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
 .								
**								
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQA: _	Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/C C	osed:	Date: _	· · · · · · · · · · · · · · · · · · ·
NCR:		,	WORK ORI	DER NON-CONFORMA	ANCE (NCF	₹)		
DATE STEF	STEP	Description of NC	Corrective Action Section			Verification		Approval
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Date		Chief Eng	QC Inspector
				,				
							. :	